

## **SUBJECT: ML Triton 4WD Actuator Protection Plate.**

Mitsubishi Australia has launched a rugged protection plate to suit 4WD Tritons made from steel.

There have been lately a number of incidents of owners operating in severe rocky terrain damaging the front differential actuator causing 4WD to stay locked in & unable to select 2WD. The damage can cost as much as \$750 to repair depending on the severity.

Members only special,  
Southside Mitsubishi will supply & fit the protection plate for

\$124.

Contact Henry Dos Santos on 9358 9555 to advantage of this offer

